

Office of the Indore Municipal Corporation, Indore
Rajmata Sindhiya zone 11

S.No. 2010

Date 23/10/2019

BUILDING SAFETY CERTIFICATE


It is certified that an inspection team headed by Mr.D.S Parihar, Structural Engineer from D.S.Parihar & Associates inspected the Daly college, 1-Residency Area, Indore (M.P.) on 21.10.2019 and found that Daly college has structurally safe and sound buildings for conducting the classes and other school activity and also comply with general safety requirements in accordance with the provision of the state.

The school is located in healthy surrounding, buildings are well ventilated and campus is neat and clean.

Further it is suggested by the Mr.D.S. Parihar to undertake the following inspection must be regularly or periodically:

1. All structural elements like wall, load bearing wall, column, beam, lintel, slab, & wall, plastering to ensure its functionally and safety.
2. Any unusual settlements of floor, wall, foundation, distressing of any members of the building.
3. Maintenance of building to ensure safety before and after monsoon period or as when required.

(Encloser - 1. Structure Engineer report)


PRINCIPAL.
DALY COLLEGE, INDORE



Signature with seal.....

Name : Asit Khare

Designation : Building Officer

Zone 11